₹.	,		/ /	' _	٠,
Approved For Re	ease-3002/40/25 + GIA-RDP	74 B00836R00010003	300	39-	0

	FILE INFO	SECRET (When Filled In)		-
• [100ec (0 3 273 s	REPRODUCTION PROHIBITED	! 0	Dec 70 10 42
	ACTION 1	6 11	16	
	3	7	18	
.	4 5	9 14	19 20	
٠	NNNT O P S E C R E T 100	0711Z DEC 70 CITE		25X1A
· [25X1A
Rps		E SALE		25)
		J. SALL		25X1A
· (REF:			25X1A
	1. CONCURS F	ULLY WITH CONCLUSIONS AND	RECOMMEND-	_ ==, •
	ATIONS PRESENTED BY THE	ACCIDENT BOARD OF ARTICL	E Ø57.	25X1A
	2. THE FOLLOWING ACT	TIONS HAVE BEEN TAKEN	IN	
	RESPONSE TO ACCIDENT BO	ARD RECOMMENDATIONS:		
	A. RECOMMENDATION	A INVOLVES A HANDBOOK CH	ANGE.	
. ui	•		25X1A	
! }	THEREFORE, NO ACTION WAS			
	B. RECOMMENDATION	B HAS BEEN COMPLIED WITH	AS — 25X1A ≠	
	FOLLOWS: INSTR	RUCTOR PILOT,	25X\A	A STATE OF THE STA
	PRESENTED A VERY THOROUGH	GH BRIEFING TO ALL PILOTS	ON Ø2 25	X1A
	DEC 70 WHILE STILL IN PI	ACE IN ADDIT	ION, ALL	
	PILOTS HAVE SINCE BEEN I	REBRIEFED ON CROSSWIND PR	OCEDURES \	
	AND TECHNIQUES AND THIS	WILL CONTINUE TO BE A PE	RIODIC	
i li			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	SUBJECT FOR NORMAL GROU			25X1A
	C. HAS INITI	ATED A SURVEY TO DETERMIN		Jan
	COST INVOLVED IN INSTAL	LATION OF A WIND MEASURIN	G DE- Open	
	VICE AS OUTLINED IN REC	OMMENDATION C. WHEN COST	S ARE	elem Jense -
	METERMINED, HQS WILL BE	ADVISED.		get .
• •	3. NEW RELATED SUBJ	ECT: PARAGRAPH 2B ABOVE	AL SO	V
,	ANSWERS PARA 2 OF REF M			

ΒT

TOPSECRET